
Harlan County Dam Tainter Gate Repairs

Ken Stark, Project Manager

August 27, 2015



US Army Corps of Engineers
BUILDING STRONG®




Presentation Outline


- Overview of Dam
- Dam Repairs
- ConstructionStatus











9 - Sluiceways

- Low/normal release
- 18 gates
- Each gate 5' x 8'
- 1 low flow bypass

2 - Irrigation conduits


- 18 Tainter gates
 - Flood control release
 - Each 40' x 30'





Harlan County Dam Repairs

- ► Tainter Gate
 Stoplogs
- **►** Tainter Gates
- ► Sluice Gates
- ► Irrigation Facilities



Construction Status





Construction Status





Construction Status

