

Summary of Lower Platte & Elkhorn Rivers

Initial Ice Report 1/6/2018 through 1/12/2019:

NO ICE JAMMING AT THIS TIME on the East end of the State.

Elkhorn

PM6 - Douglas County, on the Elkhorn Hwy 64

Latitude: 41:17:30 Longitude: 96:17:0 (Wednesday, January 9, 2019 @ 9:05AM CDT)

Temperature was 25°F. The average wind speed was 10 mph (NW). It was estimated that it was less than 11 feet bank full at this location. The channel remains 100%. It was noted: "

Elkhorn

PM2 - Douglas County, on the Elkhorn Hwy 36

Latitude: 41:22:45 Longitude: 96:18:9 (Wednesday, January 9, 2019 @ 9:30AM CDT)

Temperature was 23°F. The average wind speed was 10 mph (NW). It was estimated that it was less than 11 feet bank full at this location. The channel remains 100%. It was noted: "

Elkhorn

PM3 - Douglas/Saunders County, on the Elkhorn Hwy 92

Latitude: 41:13:51 Longitude: 96:16:41 (Wednesday, January 9, 2019 @ 10:20AM CDT)

Temperature was 26°F. The average wind speed was 10 mph (NW). It was estimated that it was less than 10 feet bank full at this location. The channel remains 100%. It was noted: "

Platte/Elkhorn

E1 – Sarpy County, Confluence of Platte and Elkhorn Rivers

Latitude: 41:8:0 Longitude: 96:19:0 (Wednesday, January 9, 2019 @ 8:10 AM CDT)

Temperature was 22°F. The average wind speed was 10 mph (NW). It was estimated that it is less than 12 feet bank full at this location.. The channel remains 100%. It was noted: " Ice cleared out of the river on January 6th.

Platte

PM4 - Douglas County, on the Platte Hwy 92

Latitude: 41:14:2 Longitude: 96:21:55 (Wednesday, January 9, 2019 @ 8:40AM CDT)

Temperature was 24°F. The average wind speed was 10 mph (N). It was estimated that it was less than 3 feet bank full at this location. The channel remains 100%. It was noted: " Ice cleared out of the river on January 6."

PM4 - Douglas County, on the Platte Hwy 92

Latitude: 41:14:2 Longitude: 96:21:55 (Wednesday, January 10, 2019 @ 8:00AM CDT)

Temperature was 20°F. The average wind speed was 11 mph (NW). It was estimated that it was less than 2 feet bank full at this location. The channel remains 100%. It was noted: " Business as usual. Frazil pans and slush moving as of 0800 on 1/10/2019. No other moving ice observed throughout this rather warm week. Water levels appears higher than typical this time of year."

Platte

PM7 - Douglas County, on the Platte Union Dike, 1/4 mile west of Hwy 275 & 3.1 miles upstream of Hwy 64

Latitude: 41:21:40 Longitude: 96:25:0 (Wednesday, January 9, 2019 @ 9:40AM CDT)

Temperature was 24°F. The average wind speed was 10 mph (NW). It was estimated that it was 3 feet bank full at this location. The channel remains 100%. It was noted: " Ice cleared out of the river on January 6th."

