

## Summary of Lower Platte & Elkhorn Rivers

### Initial Ice Report 2/17/2019 through 2/23/2019:

**Ice Thickness Summary (2/22/2019)** No specific ice thickness report as of this week's summary.

**ICE JAMMING AT THIS TIME** on the East end of the State is at the confluence of the Loup and Platte rivers near Columbus. Flooding in the lowland areas.

Information: Elevated river levels along the North Platte River at Lewellen due to Ice Jamming, and the Middle Loup River at Rockville. Platte river at Ashland.

#### **Elkhorn**

PM6 - Douglas County, on the Elkhorn Hwy 64

**Latitude: 41:17:30 Longitude: 96:17:0 (Wednesday, February 20, 2019 @ 10:30AM CDT)**

Temperature was 25°F. The average wind speed was 8 mph (SW). It was estimated that it was less than 12 feet bank full at this location. The channel remains N/A%. It was noted: "

#### **Elkhorn**

PM2 - Douglas County, on the Elkhorn Hwy 36

**Latitude: 41:22:45 Longitude: 96:18:9 (Wednesday, February 20, 2019 @ 10:45AM CDT)**

Temperature was 25°F. The average wind speed was 8 mph (SW). It was estimated that it was less than 12 feet bank full at this location. The channel remains 60%. It was noted: "

#### **Elkhorn**

PM3 - Douglas/Saunders County, on the Elkhorn Hwy 92

**Latitude: 41:13:51 Longitude: 96:16:41 (Wednesday, February 20, 2019 @ 11:30AM CDT)**

Temperature was 25°F. The average wind speed was 8 mph (SW). It was estimated that it was less than 9 feet bank full at this location. The channel remains N/A%. It was noted: "

#### **Platte/Elkhorn**

E1 – Sarpy County, Confluence of Platte and Elkhorn Rivers

**Latitude: 41:8:0 Longitude: 96:19:0 (Wednesday, February 20, 2019 @ 12:45 PM CDT)**

Temperature was 25°F. The average wind speed was 0 mph (). It was estimated that it was less than 2 feet bank full at this location. The channel remains N/A%. It was noted: "

#### **Platte**

PM4 - Douglas County, on the Platte Hwy 92

**Latitude: 41:14:2 Longitude: 96:21:55 (Wednesday, February 20, 2019 @ 10:00AM CDT)**

Temperature was N/A°F. The average wind speed was 5 mph (SE). It was estimated that it was less than 2 feet bank full at this location. The channel remains N/A%. It was noted: "

#### **Platte**

PM7 - Douglas County, on the Platte Union Dike, 1/4 mile west of Hwy 275 & 3.1 miles upstream of Hwy 64

**Latitude: 41:21:40 Longitude: 96:25:0 (Wednesday, February 20, 2019 @ 11:00AM CDT)**

Temperature was 25°F. The average wind speed was 8 mph (SW). It was estimated that it was 2 feet bank full at this location. The channel remains N/A%. It was noted: "

#### **Platte**

LS1 - Saunders County, on the Platte Hwy 6 near Ashland

**Latitude: 41:3:41 Longitude: 96:19:35 (Tuesday, February 19, 2019 @ 2:00PM CDT)**

Temperature was 22°F. The average wind speed was 0 mph (none). It was estimated that it was 2 feet bank full at this location. The channel remains N/A%. It was noted: "Ice snow covered. Open leads on both sides up to 1/2 mile in length and varying in width."

**Platte**

LS2 - Cass County, on the Platte Hwy 50 at Louisville

**Latitude: 41:0:47 Longitude: 96:9:27 (Tuesday , February 19, 2019 @ 2:30PM CDT)**

Temperature was 22°F. The average wind speed was 0 mph (None). It was estimated that it was 4.5 feet bank full at this location. The channel remains 25%. It was noted: "Open channels on both sides. Ice snow covered. Some water pooled in middle of channel on top of ice."

**Platte**

P9 - Sarpy County, on the Platte Hwy 6 & Platte River Bridge (Linoma)

**Latitude: 41:3:42 Longitude: 96:19:31 (Thursday, February 22, 2019 @ 12:00PM CDT)**

N/A

**Platte**

P7 - Sarpy County, on the Platte Hwy 31 at 204 St.

**Latitude: 41:1:27 Longitude: 96:15:29 (Thursday, February 22, 2019 @ 12:00PM CDT)**

N/A

**Platte**

P10 - Sarpy County, on the Platte Hwy 50 & Platte River Bridge

**Latitude: 41:0:53 Longitude: 96:9:28 (Thursday, February 22, 2019 @ 12:00PM CDT)**

N/A

