

Summary of Lower Platte & Elkhorn Rivers

Initial Ice Report 12/28/2018 through 1/4/2019:

NO ICE JAMMING AT THIS TIME on the East end of the State.

Elkhorn

PM2 - Douglas County, on the Elkhorn Hwy 36

Latitude: 41:22:45 Longitude: 96:18:9 (Wednesday, January 8, 2020 @ 9:00AM CDT)

Temperature was 21°F. The average wind speed was 15 mph (SE). It was estimated that less than 7 feet bank full at this location. The channel remains 100%. It was noted: "No Ice"

Elkhorn

PM3 - Douglas/Saunders County, on the Elkhorn Hwy 92

Latitude: 41:13:51 Longitude: 96:16:41 (Wednesday, January 8, 2020 @ 9:30AM CDT)

Temperature was 22°F. The average wind speed was 15 mph (SE). It was estimated that less than 5 feet bank at this location. The channel remains 100%. It was noted: "No ice"

Platte

PM7 - Douglas County, on the Platte Union Dike, 1/4 mile west of Hwy 275 & 3.1 miles upstream of Hwy 64

Latitude: 41:21:40 Longitude: 96:25:0 (Wednesday, January 8, 2020 @ 9:15AM CDT)

Temperature was 21°F. The average wind speed was 15 mph (SE). It was estimated that less than 3 feet bank at this location. The channel remains 100%. It was noted: "No ice"

Platte

PM4 - Douglas County, Hwy 92

Latitude: 41:14:2 Longitude: 96:21:55 (Wednesday, January 8, 2020 @ 08:30AM CDT)

Temperature was 21°F. The average wind speed was 15 mph (SE). It was estimated that less than 5 feet bank full at this location. The channel remains 100%. No ice.

Platte/Elkhorn

E1 - Sarpy County, on the Platte/Elkhorn Confluence of Platte and Elkhorn Rivers

Latitude: 41:8:0 Longitude: 96:19:0 (Wednesday, January 8, 2020 @ 8:00AM CDT)

Temperature was 21°F. The average wind speed was 15 mph (SE). It was estimated it was less than 5 feet bank full at this location. The channel remains 100%. It was noted: "No ice. Channels are completely open."