

Summary of Lower Platte & Elkhorn Rivers

Initial Ice Report 2/24/2019 through 3/1/2019:

Ice Thickness Summary (3/1/2019) No specific ice thickness report as of this week's summary.

ICE JAMMING AT THIS TIME on the East end of the State is at the confluence of the Loup and Platte rivers near Columbus. Flooding in the lowland areas. Platte River at Grand Island I 80 interchange has low land flooding. Information: Due to Ice Jamming, and the Middle Loup River at Rockville.

Elkhorn

PM6 - Douglas County, on the Elkhorn Hwy 64

Latitude: 41:17:30 Longitude: 96:17:0 (Wednesday, February 27, 2019 @ 9:15AM CDT)

Temperature was 9°F. The average wind speed was 15 mph (NW). It was estimated that it was less than 12 feet bank full at this location. The channel remains N/A%. It was noted: "

Elkhorn

PM2 - Douglas County, on the Elkhorn Hwy 36

Latitude: 41:22:45 Longitude: 96:18:9 (Wednesday, February 27, 2019 @ 9:35AM CDT)

Temperature was 8°F. The average wind speed was 15 mph (NW). It was estimated that it was less than 12 feet bank full at this location. The channel remains 50%. It was noted: "

Elkhorn

PM3 - Douglas/Saunders County, on the Elkhorn Hwy 92

Latitude: 41:13:51 Longitude: 96:30:8 (Wednesday, February 27, 2019 @ 10:40AM CDT)

Temperature was 10°F. The average wind speed was 15 mph (NW). It was estimated that it was less than 11 feet bank full at this location. The channel remains N/A%. It was noted: "

Elkhorn

E4 - Dodge County, on the Elkhorn Hwy 91 near Nickerson

Latitude: 41:32:19 Longitude: 96:27:17 (Thursday, February 28, 2019 @ 11:50AM CDT)

Temperature was N/A°F. The average wind speed was N/A mph (). It was estimated that it was less than N/A feet bank full at this location. The channel remains N/A%. It was noted: "

Elkhorn River-Nickerson-Looking North



Elkhorn River-Nickerson-Looking South

**Elkhorn**

E5 - Dodge County, on the Elkhorn Hwy 77 near Winslow

Latitude: 41:37:13 Longitude: 96:16:41 (Thursday, February 28, 2019 @ 11:39AM CDT)

Temperature was 16°F. The average wind speed was N/A mph (). It was estimated that it was less than N/A feet bank full at this location. The channel remains N/A%. It was noted: “

Elkhorn River-Winslow-Looking North



Elkhorn River-Winslow-Looking South



Platte/Elkhorn

E1 – Sarpy County, Confluence of Platte and Elkhorn Rivers

Latitude: 41:8:0 Longitude: 96:19:0 (Wednesday, February 27, 2019 @ 08:20AM CDT)

Temperature was 8°F. The average wind speed was 16 mph (NW). It was estimated that it was less than 11 feet bank full at this location. The channel remains N/A%. It was noted: “

Platte

PM4 - Douglas County, on the Platte Hwy 92

Latitude: 41:14:2 Longitude: 96:21:55 (Wednesday, February 27, 2019 @ 8:50AM CDT)

Temperature was 8°F. The average wind speed was 2 mph (None). It was estimated that it was less than 2 feet bank full at this location. The channel remains N/A%. It was noted: “

PM4 - Douglas County, on the Platte Hwy 92

Latitude: 41:14:2 Longitude: 96:21:55 (Thursday, February 28, 2019 @ 10:00AM CDT)

Temperature was 5°F. The average wind speed was 15 mph (NW). It was estimated that it was less than 2 feet bank full at this location. The channel remains N/A%. It was noted: “River remains solid, there has been a tiny but widening open area of running water along the East bank outside Two Rivers Cottonwood campground. this area is a couple hundred yards long but only a foot or two wide. It has been slowly getting larger over the past week.”

Platte

PM7 - Douglas County, on the Platte Union Dike, 1/4 mile west of Hwy 275 & 3.1 miles upstream of Hwy 64

Latitude: 41:21:40 Longitude: 96:25:0 (Wednesday, February 27, 2019 @ 10:00AM CDT)

Temperature was 9°F. The average wind speed was 15 mph (NW). It was estimated that it was 1.5 feet bank full at this location. The channel remains N/A%. It was noted: “

Platte

LS1 - Saunders County, on the Platte Hwy 6 near Ashland

Latitude: 41:3:41 Longitude: 96:19:35 (Wednesday, February 27, 2019 @ 1:50PM CDT)

Temperature was 13°F. The average wind speed was 0 mph (none). It was estimated that it was 2 feet bank full at this location. The channel remains N/A%. It was noted: “Open leads remain on both sides.”

Platte

LS2 - Cass County, on the Platte Hwy 50 at Louisville

Latitude: 41:0:47 Longitude: 96:9:27 (Wednesday, February 27, 2019 @ 2:15PM CDT)

Temperature was 15°F. The average wind speed was 0 mph (None). It was estimated that it was 4 feet bank full at this location. The channel remains N/A%. It was noted: “ Some large sheets moving in the open

channel.”

Platte

LN1 – Saunders/Dodge County, on the Platte Hwy 77 at Fremont

Latitude: 41:21:14 Longitude: 96:30:9 (Thursday, February 28, 2019 @ 10:15AM CDT)

Temperature was 19°F. The average wind speed was 3 mph (SE). It was estimated that it was 8 feet bank full at this location. The channel remains N/A%. It was noted: “Ice cover at Hwy 77, Fremont, solid ice covered with snow, small opening downstream of Hwy 77, between the Hwy bridge and railroad bridge.”

Platte River-Fremont-Looking West



Platte River-Fremont-Looking East

Platte

LN2 – Saunders/Dodge County, on the Platte Hwy 79 at North Bend

Latitude: 41:27:7 Longitude: 96:46:30 (Thursday, February 28, 2019 @ 10:45AM CDT)

Temperature was 16°F. The average wind speed was N/A mph (). It was estimated that it was 6 feet bank full at this location. The channel remains N/A%. It was noted: “Ice cover at Hwy 77, Fremont, solid ice covered with snow, small opening downstream of Hwy 77, between the Hwy bridge and railroad bridge.”

Platte River-North Bend-Looking East

**Platte**

P9 - Sarpy County, on the Platte Hwy 6 & Platte River Bridge (Linoma)

Latitude: 41:3:42 Longitude: 96:19:31 (Thursday, February 22, 2019 @ 12:00PM CDT)

N/A

Platte

P7 - Sarpy County, on the Platte Hwy 31 at 204 St.

Latitude: 41:1:27 Longitude: 96:15:29 (Thursday, February 22, 2019 @ 12:00PM CDT)

N/A

Platte

P10 - Sarpy County, on the Platte Hwy 50 & Platte River Bridge

Latitude: 41:0:53 Longitude: 96:9:28 (Thursday, February 22, 2019 @ 12:00PM CDT)

N/A

